

RECENT RECALLS

Vehicle		Year	Description of Recall
Hyundai Hyundai	Azera Sonata	2006-2011 2006	<p><b>NHTSA Campaign Number:</b> 18V026000</p> <p><b>Manufacturer</b> Hyundai Motor America</p> <p><b>Components</b> SERVICE BRAKES, HYDRAULIC</p> <p><b>Summary</b></p> <p>Hyundai Motor America (Hyundai) is recalling certain 2006-2011 Hyundai Azera and 2006 Hyundai Sonata vehicles. Water may enter the Anti-lock Brake (ABS) Module and result in an electrical short .</p> <p><b>Remedy</b></p> <p>Hyundai will notify owners, and dealers will install a relay in the vehicle's main junction box to prevent the risk of an ABS short-circuit while the car is turned off, free of charge. <b>The recall is expected to begin February 23, 2018.</b> Owners may call Hyundai at 1-800-633-5151. Hyundai's number for this recall is 172.</p>
Jeep	Grand Cherokee	2018	<p><b>NHTSA Campaign Number:</b> 18V048000</p> <p><b>Manufacturer</b> Chrysler (FCA US LLC)</p> <p><b>Components</b> FUEL SYSTEM, GASOLINE</p> <p><b>Summary</b></p> <p>Chrysler (FCA US LLC) is recalling certain 2018 Jeep Grand Cherokee Trackhawk vehicles equipped with a 6.2L Supercharged Engine. The fuel line may separate.</p> <p><b>Remedy</b></p> <p>Chrysler will notify owners, and dealers will inspect and, as necessary, replace the fuel line, free of charge. <b>The recall is expected to begin March 2, 2018.</b> Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U02.</p>

Chrysler	Pacifica	2017	<p><b>NHTSA Campaign Number:</b> 18V049000</p> <p><b>Manufacturer</b> Chrysler (FCA US LLC)</p> <p><b>Components</b> ENGINE AND ENGINE COOLING, ELECTRICAL SYSTEM</p> <p><b>Summary</b></p> <p>Chrysler (FCA US LLC) is recalling certain 2017 Chrysler Pacifica vehicles equipped with a 3.6l engine. The engine control software may become out of sync with the crankshaft position sensor, possibly resulting in an engine stall.</p> <p><b>Remedy</b></p> <p>Chrysler will notify owners, and dealers will update the engine control software, free of charge. The recall is expected to begin March 2, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U01.</p>
Jaguar	F-Pace	2017-2018	<p><b>NHTSA Campaign Number:</b> 18V052000</p> <p><b>Manufacturer</b> Jaguar Land Rover North America, LLC</p> <p><b>Components</b> ELECTRICAL SYSTEM</p> <p><b>Summary</b></p> <p>Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2017-2018 F-Pace vehicles. The Instrument Cluster (IC) may intermittently go blank.</p> <p><b>Remedy</b></p> <p>Jaguar will notify owners, and dealers will update the vehicle software, free of charge. <b>The recall is expected to begin February 23, 2018.</b> Owners may contact Jaguar customer service at 1-800-452-4827. Note: This recall expands the scope of vehicles recalled under 17V-678. Jaguar's number for this recall is H056.</p>

Ford Lincoln	Expedition Navigator	2018 2018	<p><b>NHTSA Campaign Number:</b> 18V058000</p> <p><b>Manufacturer</b> Ford Motor Company</p> <p><b>Components</b> VISIBILITY</p> <p><b>Summary</b></p> <p>Ford Motor Company (Ford) is recalling certain 2018 Ford Expedition and Lincoln Navigator vehicles. The second row window control modules may intermittently stop the movement of the power window. If something, such as a finger, is pinched by the window glass, the stopped window control module may prevent the window from automatically reversing. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 118, "Power-Operated Window Systems."</p> <p><b>Remedy</b></p> <p>Ford will notify owners, and dealers will inspect the second row window electronic control modules, and replace them as necessary based on their build date codes, free of charge. <b>The recall is expected to begin February 5, 2018.</b> Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18C01.</p>
-----------------	-------------------------	--------------	---

Aston Martin	DB11	2017-2018	<p><b>NHTSA Campaign Number:</b> 18V065000</p> <p><b>Manufacturer</b> Aston Martin The Americas</p> <p><b>Components</b> AIR BAGS</p> <p><b>Summary</b></p> <p>Aston Martin The Americas (Aston Martin) is recalling certain 2017-2018 DB11 V12 Coupe and DB11 V8 Coupe vehicles. The driver's frontal air bag may unexpectedly deploy due to insufficient grounding of the steering components if an electrostatic discharge occurs and the air bag clockspring is broken.</p> <p><b>Remedy</b></p> <p>Aston Martin will notify owners, and dealers will add sufficient grounding to the steering components, free of charge. <b>The recall is expected to begin March 1, 2018.</b> Owners may contact Aston Martin customer service at 1-888-923-9988.</p>
--------------	------	-----------	--

SafeCar.Gov Recall Lookup. <https://vinrcl.safercar.gov/vin/>

